



SECTION 4:

VINEYARD ROAD AT MILL ROAD ISLAND

PROPOSED IMPROVEMENTS INCLUDE: SIDEWALK, CURB & GUTTER.

ESTIMATED COST: \$50,000

OPTION 2
SIDEWALK ALONG THE NORTH EDGE
OF THE "PORKCHOP" ISLAND